13

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0269	NA	St. Marys school
Segment No.	**Total Length (m)**	
13/S-W0269/S022214	249.71	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	249.71	77.513452	13.050339	77.512922	13.048143	St marys School	SWD

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvemnets to footpath 5th cross roads of W/s at Kalyannagara in Ward No.13, Shettyhalli Sub Division	1900000	2015
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Tender		013-15-000016
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/247/2014-15	16/02/2015	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
		Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
K L Kalegowda		0.00
Phone No.	**E-Mail ID**	
9845460033		

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara Palike
Dasarahalli Division, Bangalore-560057

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Nagabhushan

Date of Inspection	Remarks
05/11/2016	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara Palike
Dasarahalli Division, Bangalore-560057

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0269

Date: 05/11/2016 Time: 14:24:30 RH 20161105142430